



Bishopbriggs War Memorial Hall

Caretaker's office is remote and isolated

Opportunity to relocate to allow visible presence at main entrance for improved supervision

Kitchen lacks connection to hall

Potential to relocate kitchen to offer direct service to main hall

Building is not sufficiently accessible

Doorways should be widened and hallway can open up to allow convenient flow of movement to accessible WC. Lesser hall may be brought to grade with rest of building for level access.

Stage is not often utilised

Stage can be removed to provide more flexible floor space in the hall.

Storage under stage is unsafe to access

A new level store room can provide adequate, safe, efficient storage with direct access to the hall

Lack of flexible space

There is the potential to expand the lesser hall with a new dividing wall to allow for flexibility of use

Functions in the Hall can be very noisy

Building fabric can be improved to minimise excessive noise leakage as well as the retention of the existing noise limiting system



Sanitary facilities do not meet current requirements

Number of WCs to be maximised within the available space.


Road access to the building is in poor condition

The existing road access could be repaired and improved, as well as new line markings to the parking areas.


Existing Interior Bishopbriggs War Memorial Hall



The two existing halls are a good size and well used although now very dated. The stage is not frequently used. The divider in the lesser hall is not fit for purpose.



The ancillary spaces are dated; modernisation is required throughout. The current storage space underneath the stage is hazardous to use. The steps towards the lesser hall make this more difficult to access. The existing terrazzo flooring is of a high quality and is hoped to be retained.



Proposed Plan Bishopbriggs War Memorial Hall

